

June 2022.Sandon All Saints, Log Book

| Description of Works and Date   | Date of Faculty | Reference to QI | Contractor   | Cost of Works incl fees £           | Details of grant aid from charitable trusts and other bodies   | Location of drawings, specifications if not filed in Log Book |
|---|-----------------|-----------------|--|-------------------------------------|--|---|
| Installation of gas lighting plant.   | 1905            |                 |  |                                     |  |   |
| New pews, organ,  | 1921 - 1923     |                 | Cornish & Gayner (North Walsham)                           |                                     | Architects Caroe and Podmore   |   |
| Repairs to Tower and windows , 1925   |                 |                 | T. Ascroft of Stafford                                     |                                     |  |   |
| Amplifier to church, 1927   |                 |                 |  |                                     |  |   |
| November 1931, the conveyance for the acquisition of Park House                 |                 |                 |  | £200 funded by Bounty of Queen Anne | From the Earl of Harrowby, together with the right of water supply from the reservoir (Helen's Tomb) and discharge of waste water to septic tank in field to west. | Stafford Record Office  |
| 1935, An agreement for the letting of a strip of land adjoining Sandon Vicarage |                 |                 |  | £2pa                                | From the Earl of Harrowby to John Charlesworth, Vicar of Sandon  | Stafford Record Office  |
| White marble tablet, Lady Margaret Susan Ryder                                  | April 1937      |                 |  |                                     |  |   |
| Electric light and organ blower   | 1948            |                 | Messrs Blackburn Stirling & Co Ltd, Hanley, Stoke-on-Trent | £250                                |  |   |
| 1948 a new organ was installed  |                 |                 |  | Insured for                         |  |   |

|  |           |  |                               |          |  |               |
|--|-----------|--|-------------------------------|----------|--|---------------|
|  |           |  |                               | £3,000   |  |               |
| Stone Tablet, Ryder family   | 1948      |  |                               | £65-10-0 | Paid by Ryder Family   |               |
| Heating supply to organ loft and console   | 1952      |  |                               |          |  |               |
| Silver Processional Cross  | 1953      |  | G of H (Guild of Handicrafts) |          | Additionally stamped with the Queen's head to denote made in the year of her coronation.   |               |
| Electric tube heating installation,  | Dec 1953  |  |                               | 757      | Plans: Messrs Bird & Son, Eccleshall   |               |
| Conversion of south aisle to Lady Chapel   | July 1957 |  |                               |          |  |               |
| Plaques in the north aisle; cross candlesticks, oak chair and plaque to Arthur George Hine   | Sept 1958 |  |                               |          | Designers; W.F. Warmington, Campden, Gloucestershire. Messrs Bridgeman of Lichfield  |               |
| Lectern in oak   | (1960)    |  | Messrs Cornes of Hanley       | £35      | Memorial to James and George Cadman  | Record Office |
| Condition Report, February 1962  |           |  | Sandy and Norris              |          |  |               |
| Replacement of Ringing Chamber and intermediate chamber timber floors and tower roof timbers |           |  |                               |          | 1962/63  |               |
| Removal, tuning, and rehangng of 3 new bells   | Mar 1963  |  | John Taylors                  |          |  |               |
| Oak screen and curtains around organ console   | Jun 1963  |  |                               |          |  |               |
| Oil fired boiler installed   |           |  |                               |          | 1973   |               |
| Parish of Sandon extended to become Parish of Sandon with Burston                            |           |  |                               |          | Pastoral Scheme dated 19th October 1983, Order in Council dated 27 <sup>th</sup> October 1983 and coming into force on the 1st November 1983 | Record Office |

|   |                          |      |                                    |         |                              |               |
|---|--------------------------|------|------------------------------------|---------|------------------------------|---------------|
| Quinquennial Review<br>1984   |                          |      |                                    |         | Forshaw Greaves and Partners | Record Office |
| Redecorating church<br>walls<br>(Application for<br>Archdeacon's Licence)<br>Faculty  | Feb 1984<br><br>May 1985 |      | Manpower<br>Services<br>Commission | 230     |                              |               |
| Rewiring of electrical<br>system and replacement<br>light fittings  | Aug 1985                 | 2.01 | T. G. Hughes                       | 1,933.7 |                              |               |
| Burial of cremated<br>remains of Rev Greenup  | Aug 1986                 |      |                                    |         |                              |               |
| The Tower; Complete<br>overhaul of roof,<br>resetting of pinnacles,<br>renewal of stonework to<br>windows, repointing of<br>stonework 1989/90 |                          | 2.30 | Bow Bells                          | 7,231.2 |                              |               |
| Repairs to stonework of<br>window in north<br>transept. Jan 1991  |                          |      | Ellastone<br>Masonry               | 465.6   |                              |               |
| Reglazing of the window<br>in the north transept. Jan<br>1991   |                          |      | Dennis Holgate                     | 764.8   |                              |               |
| Organ maintenance. Oct<br>1992  |                          |      | J. Oakes                           | 91.6    |                              |               |
| Repairs to West window,<br>glass renewal. 1993  | 1993                     |      | Williams                           |         |                              |               |
| Mullion in Baptistry<br>West window   |                          |      | Holgate                            |         |                              |               |
| New frame to window<br>on south of Chancel<br>including re-glazing  |                          |      | Sandon Estate                      |         |                              |               |
| Organ Maintenance Oct<br>1994   |                          |      | J. Oakes                           | 101.75  |                              |               |

|  |  |  |                              |         |   |  |
|--|--|--|------------------------------|---------|---|--|
| Chancel door repairs<br>April 1995             |  |  | Sandon Estate                | 570.76  |   |  |
| Repointing. May 1995                           |  |  |                              | 220.8   |   |  |
| Organ Maintenance. Oct<br>1995                 |  |  | J. Oakes                     | 103.80  |   |  |
|  |  |  |                              |         | Previous Logbook completed to here<br>but now missing |  |
| Organ tuning Oct 1996                          |  |  | J. Oakes                     | 103.80  |   |  |
| Intruder alarm                                 |  |  | Paramount<br>Security        | 342.73  |   |  |
| Quinquennial Review<br>1997                    |  |  |                              |         | Forshaw Greaves and Partners                          |  |
| Report on augmentation<br>to 6 bells, Aug 1997 |  |  | R. Daws                      |         |   |  |
| Organ Tuning Oct 1997                          |  |  | J. Oakes                     | 126.30  |   |  |
| West Window repair Jan<br>1998                 |  |  | Stained Glass<br>Designs     | 414.00  |   |  |
| West window further<br>repairs July 1998       |  |  | Stained Glass<br>Design      | 182.00  |   |  |
| Repairs to gutters Oct<br>1998                 |  |  | P. Arnold                    | 370.38  |   |  |
| Organ tuning Oct 1998                          |  |  | J. Oakes                     | 103.80  |   |  |
| Thermostat Feb 1999                            |  |  | P. Morton                    | 120.0   |   |  |
| Alarm System Feb 1999                          |  |  | Paramount<br>Security        | 99.88   |   |  |
| Organ tuning                                   |  |  | J. Oakes                     | 109.0   |   |  |
| Guttering renewal                              |  |  | T. Parnell                   | 258.0   |   |  |
| Repointing outside                             |  |  | Allied Technical<br>Services | 4112.50 |   |  |
| Boiler maintenance, July<br>2000               |  |  | P. Morton                    | 127.19  |   |  |
| Stripping gloss paint<br>interior, July 2002   |  |  | A.G. Godwins                 | 10,500  | £3,000 Onxy Trust                                     |  |

|  |  |  |  |                 |  |                 |
|--|--|--|--|-----------------|--|-----------------|
| Stripping Gloss paint interior, Aug 2000   |  |  | A.G. Godwins                                     | 13,312          |  |                 |
| Architects' Fees Oct 2000                  |  |  | Forshaw Greaves                                  | 1,406.5         |  |                 |
| Mural Inspection, January 2001             |  |  | Lisa Shekada                                     | 234.00          |  |                 |
| Church Cleaning, April 2001                |  |  | 1 <sup>st</sup> Time                             | 180.85          |  |                 |
| Organ repairs Sept 2001                    |  |  | J. Oakes   | 786.50          |  |                 |
| Organ maintenance Oct 2001                 |  |  | J, Oakes   | 115.55          |  |                 |
| Boiler repairs Nov 2001                    |  |  | P. Morton  | 780.22          |  |                 |
| North east window repairs. Dec 2001        |  |  | G. Chaplin                                       | 1,071.5         |  |                 |
| Report on Erdeswicke monuments. Sept. 2002 |  |  | Michael Eastham                                  |                 |  |                 |
| Treble Bell installed                      |  |  | Wheel by Phil Gay; Installation by Matthew Higby |                 | Bell cast in 1960 at Whitechapel and obtained through the Keltek Trust |                 |
| Hearing Aid Loop                           | (List B)<br>26 <sup>th</sup><br>November<br>2003 |  | John Weaver                                      | £400            | Implemented  |                 |
| New oil boiler Nov 2004                    |  |  | Mellor & Mottram                                 | 6,000           |  |                 |
| Quinquennial Review 2004                   |  |  |  |                 | Graham Holland Associates  |                 |
| Asbestos Report, Nov 2004                  |  |  | IOM Consulting                                   |                 |  |                 |
| Installation of oil tank, 2004/05          |  |  | Mellor and Motram                                | £1,550 plus vat |  |                 |
| Electrical upgrading and                   |  |  | Peake Electrical                                 | £4,000          | Subsequent dispute and resolution                                      | Stafford Record |

|   |                               |  |   |                    |  |                           |
|---|-------------------------------|--|---|--------------------|--|---------------------------|
| rewiring, 2004/05   |                               |  | Services  | plus vat           |  | Office                    |
| Minor roof repairs  | (List B)<br>15th June<br>2005 |  | R.S.Miller<br>(Roofing)<br>Wolverhampton<br>Ltd | £1,735<br>plus vat | As per Drawing No 6084.3.1   | Stafford Record<br>Office |
| Wooden cover to<br>Norman Font  |                               |  | Dai Hitchings                                   |                    |  |                           |
| Roof Repairs incl. steel<br>"A" frame to<br>Nave/Chancel parapet, &<br>drainage<br>June 2006/March 2007 |                               |  | Linfords  | 160,000            | English Heritage £104,000<br>All Churches Trust<br>Rest fund raising | Stafford Record<br>Office |
| Billy Sargent plaque<br>June 2006   |                               |  | Signmakers                                      | 110                |  |                           |
| Provision of new<br>soakaways and relaying<br>in part stone channels<br>2006/07                         |                               |  | Linfords  |                    | Architects, Brownhill Hayward Brown                                  |                           |
| Modifications to oil<br>boiler, 2007  |                               |  | W.T.Morton &<br>Sons                            | 4,108              | After dispute with Mellor and Motram                                 | Stafford Record<br>Office |
| Archaeological Report,<br>Feb 2008  |                               |  |   |                    | On trenches for drainage   |                           |
| New main gate   |                               |  | (W.H.Homes?)                                    | (£250)             | Tanalised Swedish Redwood  |                           |
| 4 <sup>th</sup> bell clapper reset with<br>leather. 12 May 2009   |                               |  |   |                    | K. Pemberton   |                           |
| Balcony window lower<br>pane reset. 7 Nov. 2009   |                               |  |   |                    | K. Pemberton & T Cochrane  |                           |
| Architects Drawings for<br>toilet in storeroom<br>June 2009   |                               |  |   | 1,100              |  | Stafford Record<br>Office |
| Quinquennial Review<br>November 2010  |                               |  |   |                    | Brownhill Hayward Brown  |                           |
| Bell Tower electrics<br>2010  |                               |  | L&L Electrics                                   | 770                | PCC and Bellringers  |                           |
| Electrical Certificate for  |                               |  | R. Haynes                                       |                    |  |                           |

|  |                        |      |   |        |  |                        |
|--|------------------------|------|---|--------|--|------------------------|
| Tower Additions 21/1/10  |                        |      |   |        |  |                        |
| Ringling Chamber lime-washed, wood varnished and new carpet April 2010                           |                        |      |   |        | Bellringers  |                        |
| Agreement to toilet drainage September 2010  |                        |      |   |        | Agreement by Lord Harrowby to the toilet drainage being connected to the drainage system of the former vicarage  |                        |
| No 3 Bell stay replaced Nov 2010   |                        |      | K. Pemberton                              |        |  |                        |
| Graphite paste on Hasting stay slides  |                        |      | K. Pemberton                              |        |  |                        |
| 6 New Bell Ropes June 2011   |                        |      | Matthew Higby & Co Ltd,<br>Timsbury, Bath | 892.80 |  |                        |
| Rebuild Front Boundary wall  |                        | 5.04 |   |        |  |                        |
| New Toilet Room & relocation of WW boards & entrance new stone floor slabs<br>Summer 2012        | May 2011 &<br>May 2012 |      | Croft Conservation                        | 57,200 | Garfield Weston £7,500<br>Landfill Communities Fund £22,349<br>All Churches Trust £3,000<br>JCB Charitable Trust £2,000<br>HMRC Gift Aid Refund £7,300<br>Balance, Congregation, gifts, events | Stafford Record Office |
| Replacement heating system (revealing brick lined vault under west end raised floor) summer 2012 | May 2011 & May 2012    |      | W.T Morton & Son                          | 27,400 | Staffordshire Historic Churches Trust £3,000<br>Balance, Congregation, gifts, events,<br>HMRC Gift Aid refund<br>Heating set to 15c (subsequently set to 16c) frost 5c                         | Stafford Record Office |
| Replacement Bell stays   |                        |      | P. Gay                                    | 21     |  |                        |
| No 5 Bell slider stop replaced   |                        |      | K. Pemberton                              |        |  |                        |
| No 5 Bell stay replaced April 2012   |                        |      | K. Pemberton/<br>M. Capper                |        |  |                        |

|  |  |  |   |          |   |  |
|--|--|--|---|----------|---|--|
| Inspection of lead valley gutter between the nave and south aisle roofs April 2013 |  |  | A.Mathias of Brownhill Hayward Brown            | £216     |   |  |
| Repairs to stone floor slabs May 2013  |  |  | Croft Building and Conservation Ltd             | £3,944   | Nave, north aisle and Chancel and circular holes in Chancel floor Grant of £1,000 by SHCT |  |
| No 4 Bell stay replaced September 2013   |  |  | K. Pemberton/<br>M. Capper                      |          |   |  |
| Report on bells. Nov 2013  |  |  | D. Jack   |          | NSACR Bell Advisor  |  |
| No 3 Bell slider stop replaced   |  |  |   |          |   |  |
| Replacing tiles east facing valley 15/7/13   |  |  | Miller Roofing                                  | 108      |   |  |
| Oil boiler service 5/8/13  |  |  | W.T. Morton                                     | 226.40   |   |  |
| Bell stays   |  |  | P. Gay  | 11       |   |  |
| No 2 Bell bearing housing refaced and repacked December 2013                       |  |  | John Taylor Bell Foundry (Loughborough) Limited | 1,424.40 |   |  |
| No 3 Bell stay replaced February 2014  |  |  | K. Pemberton/<br>I. Kinnersley                  |          |   |  |
| Report on Bells March 2014   |  |  | G. Burton                                       |          | DAC Bell Advisor  |  |
| Replace halogen lights with LEDs 2014  |  |  | Congregation                                    |          |   |  |
| Fit grease nipples to clapper bearings and grease, May 2014                        |  |  | K. Pemberton                                    |          | Nipples £24   |  |
| Organ maintenance and tuning 20/10/14  |  |  | John Oakes Organ                                | 164      |   |  |
| Alarm maintenance 24/10/14   |  |  | Paramount Security                              | 144      |   |  |



|   |                               |  |                           |        |   |                                      |
|---|-------------------------------|--|---------------------------|--------|---|--------------------------------------|
| Oil boiler repairs<br>12/12/14  |                               |  | W. T. Morton              | 336.94 |   |                                      |
| Theft of lead from<br>Vestry and north aisle<br>roof, on or about the<br>night of the 9 <sup>th</sup> May<br>2015   |                               |  |                           |        |   |                                      |
| Report on Coat of Arms<br>6/7/15  |                               |  | Hirst<br>Conservation     | 1,140  |   |                                      |
| Vestry replacement table<br>July 2015   |                               |  |                           |        | Donated by Mrs J. Dawson<br>Old stained/wood-wormed oak table<br>dismantled and some oak stored |                                      |
| Disposal of Bier, August<br>2015  |                               |  |                           |        | Metal concertina type, not now required   |                                      |
| 6 Muffles Oct 2015  |                               |  | Big Wilfs Bell<br>Muffles | £224   |   |                                      |
| Quinquennial Review<br>October 2015   |                               |  |                           |        | Brownhill Hayward Brown   |                                      |
| Organ maintenance and<br>tuning 5/11/15   |                               |  | John Oakes<br>Organ       | 164    |   |                                      |
| Asbestos Survey and<br>Management Plan<br>29 Nov. 2015  |                               |  | DJ Surveying              | £395   |   | Stafford Record<br>Office and Vestry |
| Electric Installation<br>Condition Report<br>18/11/15   |                               |  | Squires Electrical<br>Ltd | 240    |   |                                      |
| Re-roofing of south<br>pitch, south aisle; Porch<br>pitches with new gutters<br>and downspouts; Gablet<br>window sill repairs;<br>repairs to Tower louvres;<br>provision of galebreaker<br>new hatch; painting of<br>bell frame | 8 <sup>th</sup> April<br>2015 | A,<br>a),<br>b),<br>d)<br><br>B,<br>c) | Miller Heritage           | 65,869 | Listed Places of Worship Roof Repair<br>Fund £50,049<br>Vat recovery £10,919<br>PCC £5,000      | Stafford Record<br>Office            |

|  |                              |  |                                |        |                                    |  |
|--|------------------------------|--|--------------------------------|--------|------------------------------------|--|
| January 2016<br>Replacement Vestry &<br>north aisle roofing<br>following theft of lead   | 27 <sup>th</sup> Oct<br>2015 |  |                                |        |                                    |  |
| Vestry replacement<br>carpet, redecoration,  |                              |  |                                |        |                                    | £8,531 from Ecclesiastical Insurance for<br>damage.<br>Greyfriars Carpets and Barton<br>Decorators |
| Copper Beech Spider<br>and pulleys for bell ropes<br>in Ringing Chamber<br>February 2016 |                              |  | K.D.Pemberton                  |        |                                    |  |
| Decorated Incumbents'<br>List for porch 2/16   |                              |  | Mrs Diane<br>Bradley           |        |                                    |  |
| Lighting repairs 19/3/16   |                              |  |                                | 456.31 |                                    |  |
| 2 collection plates 2/16   |                              |  |                                |        | Made by Richard Bennett in oak     |  |
| New wicket gate and<br>fence in the lower<br>churchyard. 2/16                            |                              |  | Stephen and<br>Lesley Brandon  |        |                                    |  |
| Sandon Church website.<br>2/16   |                              |  |                                |        | Donated by Janet and Chris Dawson. |  |
| Bell spares/ new<br>greasing nipples 19/3/16   |                              |  | John Taylor bells              | 216    |                                    |  |
| Lettering for Bell Board   |                              |  | TCE Ltd                        | 115.78 | Board by K. Pemberton              |  |
| No 4 Bell stay replaced  |                              |  | K. Pemberton/<br>I. Kinnersley |        |                                    |  |
| Organ Protection from<br>roof works 16/10/16   |                              |  | John Oakes<br>Organ            | 82     |                                    |  |
| Incinerator ashes<br>removed   |                              |  | Mr. Millington                 |        |                                    |  |
| Replacement Audio<br>System  | 24 Oct<br>2017               |  | Stagecraft<br>Systems          | 7,446  |                                    | Vestry then SRO  |
| Provision of Kath  | 2017-                        |  | Robert Dewberry                |        |                                    | Stafford Record  |

|  |  |  |   |         |  |                           |
|--|--|--|---|---------|--|---------------------------|
| Dewberry memorial bench                                    | 017201<br>List B   |  |   |         |  | Office                    |
| Organ maintenance and tuning 28/10/17                      |  |  | John Oakes<br>Organ                                 |         |  |                           |
| Boiler lugs welded on and maintenance Dec. 2017            |  |  | D. J. Homer   | 326.98  | Heating raised to 16c                                    |                           |
| Tiles nailed down east facing valley 5/18                  |  |  | Miller<br>Conservation                              |         |  |                           |
| Graveyard west fence and footpath gate replaced Jan 2018   |  |  | Stephen Brandon                                     |         |  |                           |
| Introduction of a memorial seat                            | List B,<br>08/02/2018  |  | The Dewberry<br>family                              |         | Kath Dewberry  |                           |
| Replacement of Lightning conductor grounding November 2018 | 2018-<br>026899<br>List A                                    |  | Central High Rise<br>Limited                        | £778.80 |  | Stafford Record<br>Office |
| Raise level of audio equipment                             |  |  | Stagecraft  | 228     |  |                           |
| Replace some PIRs on alarm system 8/18                     |  |  | Paramount<br>Security                               | 240     |  |                           |
| Augmentation Peal Board                                    | 2018-<br>026845<br>Archdeacon's<br>Approval<br>9 Oct<br>2018 |  | TCE Ltd<br>Newstead<br>Industrial Estate<br>ST4 8HX | £96     | Lettering.<br>Board made and donated by Ken<br>Pemberton | Stafford Record<br>Office |
| Main gate, Vestry and Chancel doors outside oiled          |  |  | K. Pemberton/<br>P. Hirrel                          |         |  |                           |
| Organ maintenance and tuning 10/18                         |  |  | Oakes Organ<br>Services                             |         |  |                           |
| Oil boiler service 12/18                                   |  |  | D. J. Homer   | 154.98  |  |                           |

|   |   |  |   |         |  |                                   |
|---|---|--|---|---------|--|-----------------------------------|
| Oil Boiler, 7/12/18                                 |   |  | D.C. Heating and Plumbing Solutions                       | 231.99  | Re-new oil line & re-fit oil filter and fire valve |                                   |
| Area for the Burial of Cremated Remains             | 15 April 2019                                 |  |   |         | First burial 14 June 2019                          | Vestry and Stafford Record Office |
| Replacement of Inner Porch stone step               | 2019-030603 Archdeacon's Approval. 15/03/2019 |  | Bradshaw and Wright Stonemasons 8 <sup>th</sup> June 2019 | 1,420   |  | Stafford Record Office            |
| Resurfacing Church tarmac paths                     | 2019-031491 List A 6 <sup>th</sup> March 2019 |  | Dawkes & Co Ltd 24/25 June 2019                           | £10,389 |  | Stafford Record Office            |
| Replacement oil feeder pipe, tank to boiler         |   |  | Lawrence Littler SCPH, Stonebench Farm June 2019          | £280    |  | Stafford Record Office            |
| Church Plate Valuation                              |   |  | Dooer Valuations  | 696.96  |  | Vestry and Stafford Record Office |
| Replacement of 3 lights under the balcony with LEDs |   |  | 6 July 2019   | £7.50   |  |                                   |
| Organ maintenance and Tuning                        |   |  | Oakes organ tuning  | 178     |  |                                   |
| Bell clapper bearings greased September 2019        |   |  | K. Pemberton/<br>I. Kinnersley                            |         |  |                                   |
| Yew trees pruning and raising canopy                | 2019-043827                                   |  | Keith Parton  | £900    | 30/31 October 2019                                 | Stafford Record Office            |

|   |  |  |                                |                 |   |  |
|---|--|--|--------------------------------|-----------------|---|--|
| Replacement of Gallery southside halogen light with 30w LED floodlight                        |  |  | 26 <sup>th</sup> November 2019 | Light<br>£49.80 | Bell Skyline LED Floodlight, 30w, 2,500 lumens, colour cool, Temp 4000k, IP 65, 35,000 hours, 5 years guarantee   |  |
| 5 oak crosses on unmarked graves  |  |  | 10 December 2019               |                 | Made and donated by JK Erected by CBCC TWG  |  |
| Prayer Request Board  |  |  | February 2020                  |                 | Oak reclaimed from Vestry desk. Made by JK  |  |
| Nave south side pews, floor screws tightened  |  |  | !8 February 2020               |                 | Church Building and Churchyard Committee (CBCC) Tuesday Working Group (TWG)   |  |
| Wooden panel left of the Lady Chapel altar missing part replaced                              |  |  | 25 <sup>th</sup> February 2020 |                 | CBCC TWG (JK)   |  |
| Wooden top to 1669 font treated for woodworm and Danish Oil after damage by flooding in 2015. |  |  | 3 <sup>rd</sup> February 2020  |                 | CBCC TWG  |  |
| Mower Service   |  |  | S L Servicing Stone            | £86             |   |  |
| Free standing cupboard, by Ringing Chamber steps, treated for woodworm                        |  |  | 10 <sup>th</sup> March 2020    |                 | CBCC TWG  |  |
| CHURCH CLOSED due to Covid 19 pandemic  |  |  |                                |                 | On 27 <sup>th</sup> March 2020 the Archbishops required that all churches be closed for all services. 2 <sup>nd</sup> April notice on church door prohibiting all entry, except Churchwarden Mrs Elizabeth Jarrett who visits the church once a week. Utilities and alarm remained on except for electricity and water turned off in toilet room. Church plate removed to |  |

|   |  |              |                                    |                   |   |        |
|---|--|--------------|------------------------------------|-------------------|---|--------|
|   |  |              |                                    |                   | safe and Vestry.<br>Graveside only committals. Burial of Neville Goodwin, Emeritus Churchwarden, 27 <sup>th</sup> March 2020.<br>22 <sup>nd</sup> April, grass mowing only allowed to and around recent burials |        |
| 6 <sup>th</sup> May. Limited access allowed to church by designated/nominated persons.  |  |              |                                    |                   | Bishop of Lichfield's email   |        |
| 8 <sup>th</sup> May 2020.<br>Replaced wired consumer fuse box beside ringing chamber stairs, with a twin RCD controlled consumer unit with MCBs; Replace 30mA rcd socket in Vestry; test of portable equipment and system Electrical Test Certificate |  | 2015<br>7.02 | Squires Electrical Ltd of Stafford | £550.<br>Excl vat |   | Vestry |
| Covid-19 amendment  |  |              |                                    |                   | Following Archdeacon's advice, the PCC decided that grass mowing could start on 26 <sup>th</sup> May 2020   |        |
| Church reopens for private prayer   |  |              |                                    |                   | Sunday 21 <sup>st</sup> June 2020, between 10am and 2pm. Attendance of about 8 people.<br>Sunday 5 <sup>th</sup> July 2020  |        |
| Bell infrastructure inspection after no ringing for 14 weeks  |  |              | K.Pemberton                        |                   | 7 <sup>th</sup> July. Satisfactory.   |        |
| Church re-opens for Team service for 24 people, with Covid-19 social distancing   |  |              |                                    |                   | Sunday 12 <sup>th</sup> July 2020   |        |

|   |  |  |   |                 |  |  |
|---|--|--|---|-----------------|--|--|
| Replacement of outside floodlight on southeast corner of Chancel with LED |  |  | K. Pemberton/I. Kinnersley                | £49.80          | 30w Bell Skyline<br>18 <sup>th</sup> August 2020   |  |
| Chancel and Vestry doors  |  |  |   |                 | Outside surfaces painted with boiled linseed oil 20 <sup>th</sup> October 2020   |  |
| White, side (oak) gate  |  |  | John Kenyon                               |                 | Latch end spindle and lower rail (part) and spring replaced. 27 <sup>th</sup> October 2020   |  |
| CHURCH CLOSED due to Covid 19 pandemic accept for private prayer          |  |  |   |                 | From 5 <sup>th</sup> November 2020 until 2 <sup>nd</sup> December, by Government Regulation. Church available for private prayer each Sunday fortnight from 10am until 11.30. 4 in total |  |
| Fire Risk Assessment  |  |  |   |                 | 24 <sup>th</sup> November by Ken Pemberton   |  |
| Quinquennial Inspection   |  |  | Adrian Mathias of Brownhill Hayward Brown | £834            |  |  |
| Team Services fortnightly   |  |  |   |                 | 13 <sup>th</sup> December onwards. 12 Team Services at All Saints. In January Team Services only held at Weston  |  |
| 50 hawthorn whips on former vicarage boundary                             |  |  | Beechwoodtrees Ireland                    | £30.49          | Planted and donated by Ken and Rose Pemberton  |  |
| Quinquennial Review December 2020   |  |  |   | £720            | Brownhill Hayward Brown  |  |
| Alarm System changed. 10 <sup>th</sup> December 2020                      |  |  | Cress Security LTD, Stafford              | £1,135 excl vat | Paramount PIR system removed. Replaced by wireless system with additional sensors on external doors of the Chancel and Vestry with remote monitoring.                                    |  |
| Oil boiler service. 10 <sup>th</sup> December 2020                        |  |  | D.J. Homer, Rugeley                       | £148.99         |  |  |
| KEEP CLEAR sign on gate. 3 <sup>rd</sup> January 2021                     |  |  | K. Pemberton                              | £21.60          | Produced by TCE Ltd, Stoke-on-Trent. Donated by Ken Pemberton  |  |
| Fire Extinguisher   |  |  | B.W.Belcher &                             | £96.00          | 1 foam extinguisher replaced. CO2  |  |

|   |  |  |  |                            |  |  |
|---|--|--|--|----------------------------|--|--|
| Service. 10 <sup>th</sup> March 2021                                  |  |  | Son Ltd  |                            | extinguisher swapped to Inner Porch  |  |
| COVID 19 Services   |  |  |  |                            |  |  |
| Electric Switches changed. 1 <sup>st</sup> May 2021                   |  |  | Squires Electrical Ltd. Unit 7A Romford Road, Stafford | £191.25                    | Boiler Room. Replaced 2 switched spurs<br>Ringing Chamber. Replaced light switch and 1 isolator.<br>All new ones damp proof.<br>Balcony stairs ceiling light replaced with LED fitting.      |  |
| Cut back hedge to former vicarage. April/May 2021                     |  |  | Tuesday Working Group                                  |                            |  |  |
| Boiler Room cill cleared. April 2021                                  |  |  | Tuesday Working Group                                  |                            |  |  |
| Churchyard steps' signs. 1 <sup>st</sup> June 2021                    |  |  | Tuesday Working Group                                  |                            | Sign faces produced by TCE Ltd, Stoke-on-Trent.  |  |
| Surface water drainage. 1st June 2021                                 |  |  | Tuesday Working Group (Don Mitchell)                   |                            | Gullies and drains, either side of the Chancel, cleared to soakaways by high pressure jet  |  |
| Oil Tank Battery replaced. 7 <sup>th</sup> Sept 2021                  |  |  | Ken Pemberton  | Previously bought in batch | Watchman Transmitter, Power tube. Part of Baseefa02ATEX0043, 6 volts<br>Manufactured by Sensor Systems<br>Watchman Ltd, N Ireland<br>Tel +44(0)2838321111<br>Email, sales@sensor-systems.com |  |
| Vestry top light in the window fell out. 5 <sup>th</sup> October 2021 |  |  | Tuesday Working Group                                  |                            | Temporarily wedged in, and siliconed in on 26 <sup>th</sup> October 2021   |  |
| Oak chair 21 <sup>st</sup> October 2021                               |  |  | Ken Pemberton  |                            | Repaired, re-stained, re-polished  |  |
| Ringing Boards 24 <sup>th</sup> October 2021                          |  |  | Ken Pemberton  |                            | Board for the Marriage of H.R.H Prince William of Wales with Miss Catherine Middleton and birth of H.R.H Prince George of Cambridge and Board for Quarter Peal for birth of Princess         |  |



|  |  |  |  |         |   |  |
|--|--|--|--|---------|---|--|
|  |  |  |  |         | Charlotte of Cambridge  |  |
| Storeroom light replaced with LED fitting and boiler power socket replaced with damp-proof socket. |  |  | Squires Electrical                             | £115    | 26 <sup>th</sup> October 2021   |  |
| Bell Clapper axles greased 9 <sup>th</sup> December  |  |  | Ken Pemberton & Ian Kinnersley                 |         | 5 out of the 6. Treble has an axle that does not require greasing. 3 and 4 clappers extreme wobble when ringing.                          |  |
| Outside floodlight on Vestry corner failed 17 <sup>th</sup> December                               |  |  | Squires Electrical                             | £50     | Fitting only as housing and bulb already available  |  |
| Annual boiler maintenance and wc inner flushing mechanism replaced 19 <sup>th</sup> December       |  |  | Dan Homer, Rugeley                             | £196.97 |   |  |
| Oil boiler repaired 4 <sup>th</sup> March 2022   |  |  | Dan Homer, Rugeley                             | £656.38 | Whirred but did not fire-up. 27 <sup>th</sup> February. 17 years without a major repair. Replaced motor, solenoid, capacitor, control box |  |
| Fire extinguishers. 5 <sup>th</sup> April 2022   |  |  | B.W Belcher & Son Ltd. Uttoxeter               | £78.00  | 2 Foam fire extinguisher cylinders serviced and new seals. 1 service/exchange, 2 kg Co2 with 10 year overhaul.                            |  |
| South aisle low cupboard   |  |  |  |         | Corner beading re-fixed. 6 <sup>th</sup> April 2022   |  |
| Outer porch ceiling light failed   |  |  | Squires Electrical                             |         | Replaced by new housing and LED   |  |
| Outside Doors May/June   |  |  | Tuesday Working Group (Richard Jarrett)        |         | Boiled linseed oil applied  |  |
| Boundary Gates, Summer 2022  |  |  | Tuesday Working Group (Richard Jarrett, Casper |         | Boiled linseed oil applied  |  |

|  |  |  |   |         |  |  |
|--|--|--|---|---------|--|--|
|  |  |  | Schone)                                   |         |  |  |
| Bell clappers refurbished<br>June 2022   |  |  | John Taylor & Co<br>Loughborough          | £861.60 | Receive clappers 2, 3 &4, reface clapper ball, check all threads, re-bush the clapper tops with resiliently mounted precision oilite bushes and repaint and rehang |  |
| No 5 Bell stay dingle bolt sheared and casting splayed. 1 November 2022                                |  |  | Ken & Rose<br>Pemberton & Don<br>Mitchell |         | Casting heated to bend back into shape and replacement bolt fitted   |  |
| Replace west-end high LED light 100W on 15 November 2022   |  |  | Phil Barber                               | £98     | New Led 50W 6,000 lumens, cool white from WT Lighting. (11/11/22) (Others need to be warm white and slightly less lumens)  |  |
| Replace north aisle west end LED light and balcony north end halogen on 29 <sup>th</sup> November 2022 |  |  | Squires Electrical                        | £177.60 | New LEDs 30W 2,500 lumens, colour cool, temp 4,000k  |  |
| Pascal candle, 3 <sup>rd</sup> January 2023  |  |  |   |         | Upper platform joined to pedestal by dowel glued to pedestal end only  |  |
| No 4 Bell stay broken and replaced. 9 <sup>th</sup> January 2023                                       |  |  | Ken Pemberton                             | £5      |  |  |
| Vestry socket replaced. January 2023   |  |  | Squires Electrical                        | £84     | To include 2 USB outputs and spur for alarm hub  |  |
| 3 new bell ash stays<br>January 2023   |  |  | Phil Gay                                  | £30     | As spares and planed   |  |
| Oil boiler failure of pressure valve. February 2023  |  |  | D.J. Homer                                | £577.09 |  |  |
| Porch external light replaced. March 2023  |  |  | Squires Electrical                        |         |  |  |
| Twin socket switch replaced and Porch  |  |  | Squires Electrical                        | £72     | Switch top right of Nave. Porch wiring wrongly connected at original   |  |

|  |  |  |   |         |   |  |
|--|--|--|---|---------|---|--|
| circuit fault repaired.<br>28 <sup>th</sup> March 2023.                |  |  |   |         | installation.   |  |
| Shelving and partitions<br>in Storeroom                                |  |  | N. Wilson,<br>(Tuesday<br>Working Group)    | £93     | Including barrier to electrical apparatus   |  |
| Lead downspout outside<br>south wall of Chancel                        |  |  | Ken Pemberton                               |         | Several bracket fixings loose from wall.<br>Temporary fixing of lead bracket to<br>wall   |  |
| 4 Ringing Boards<br>May 2023, put up in July<br>2023                   |  |  | Ken Pemberton<br>& TEC Signs of<br>Newstead | £364.80 | 2012, Diamond Jubilee and London<br>Olympics; 2015, 70 <sup>th</sup> anniversary of end<br>of Second World War; 50 <sup>th</sup> anniversary<br>of start of construction of Trent and<br>Mersey Canal and 300 <sup>th</sup> anniversary of<br>the birth of James Brindley; 2022,<br>Platinum Jubilee. |  |
| Fire Extinguishers<br>service. May 2 <sup>nd</sup> 2023                |  |  | B.W.Belcher &<br>Son Ltd                    | £33.60  |   |  |
| Alarm faults in setting<br>2 <sup>nd</sup> May                         |  |  | Cress Alarms                                |         | Moved the main hub to behind the<br>organ console and the repeater hub<br>recently placed there moved to Vestry   |  |
| Cracked bell stay on 3 <sup>rd</sup><br>replaced. Spring 2024          |  |  |   | Free    | Replaced by Ken Pemberton and<br>Lindsey Gregory  |  |
| “Sandon Church” chest<br>lid reinforced with ribs.<br>March 2024       |  |  | Gerry George                                | Free    |   |  |
| Cupboard under Ringing<br>Chamber stairs<br>2 <sup>nd</sup> April 2024 |  |  |   |         | No signs of woodworm in the softwood<br>temporary supports for the stairs.<br>Cleared for storage of children’s crafts  |  |
| New heating controller<br>fitted 23 <sup>rd</sup> April 2024           |  |  | Dan Homer                                   | £1,120  | With wifi potential   |  |
| Replace LED in north<br>aisle 24 <sup>th</sup> April                   |  |  | Squires Electrical                          | £80     | New LED 30W 2,500 lumens, colour<br>cool, temp 4,000k   |  |